



No. 3 - March 2015

Check your ACME couplings and stay safe



The Kosan Crisplant Group



Locate your KC ProSupply contacts »

Daily use takes its toll on ACME couplings, but assessing exactly when they are due for replacement isn't all that easy. An ACME wear gauge set is a simple tool that helps you make that assessment before a potentially fatal coupling failure occurs.

To test the coupling, simply attempt to screw the gauge and the coupling together. If the gauge fits, the coupling has failed the test and should be replaced.

We supply the ACME wear gauges in a specially made hard case that protects them from damage during storage and transport. The case also includes a service report that helps you keep track of the performed checks - all for the sake of safety.

[Get in touch with KC ProSupply to learn more »](#)



Meet KC ProSupply at these fine events - [Click for details](#)